


Figure 1



## THE LIFE CYCLE APPROACH










Figure 3




Figure 4




Figure I

Task Options Task			Туре				
C All C Open Tasks C Scheduled Tasks C Completed Tasks C Canceled Tasks Repl							
			ntenance airs				
						ace	
					Servi	ces	1 1
		Misc					
Building	Roof	Type	Task	Schd			
Building 3	Roof 3	Maintenance	Good, Maintain Roof	11			
Building 3	Roof 3	Maintenance	Good, Maintain Roof	11			
Building 3	R0013	Mainlenance	Good, Maintain Roof	11			
Building 3	Roof 3	Repairs	Repairs Required, Minor	11			
Building 3	Roof 3	Repairs	Repairs Required, Minor	11			
Building 3	Roof 3	Repairs	Repairs Required, Minor	11			
Building 3	Roof 3	Repairs	Repairs Required, Major	11			
Building 3	Roof 3	Restore	Restore Immediate	11			

Figure 6

-: TRIM REPORT: ABC Company	
	254
TRIM Report	
Cover with Photos	
Report Interpretation	
Table of Contents	:
INTRODUCTION	- 1
EXECUTIVE SUMMARY - Table of Contents	
Overview	
Roofing Inventory Examined	
Roof Membrane Distribution	`
Square Footage Distribution	
Age Analysis	
Urgency Categories	;
Roof Type Analysis	
Budget Summary	1, 14
Budget Detail (By Building)	
Budget Detail (By Roof)	
Region - None	
None Cover Page	
None Cover Page with Photos	X.
Select All Reports Select All Photos 🔽 Current Inspe	ction
Preview Print Exit	

Figure 7




Figure 8